

Work Order (Bid Form)

Knoxville/Knox County Community Action Committee



WORK ORDER INFORMATION

Work Order Name: WO/80008KN0813/1

Work Order Type: Weatherization

Audit Name: 80008KN0813-AUDIT

CLIENT INFORMATION

Client Name:

Address:

Client ID: 80008KN0813

Alt. Client ID: KNOX

AGENCY INFORMATION

Agency: Knoxville/Knox County CAC

Address: P.O.Box 51650

Knoxville, TN 37950-1650

Agency Phone: (865) 244-3080

Fax: (865) 544-1647

Email Address: jason.estes@cachousing.org

Company Name & License Number	r:	
Contractor's Signature:		

COMMENT

Single Family Dwelling

Contractor to follow 2006 International Residential Code as adopted by the City of Knoxville or Knox County as applicable.

City

Home built in 1980

Client Name:

Client ID: 80008KN0813
Alt. Client ID: KNOX

Work Order (Bid Form)

Work Order Name: WO/80008KN0813/1 Report Run On: 5/8/2010 DOE Weatherization Assistant Version 8.6.0

Page 1 of 8

Measures

Measure 1 DWH Pipe Insulation Comment					Componen	ts			Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
		Includes labor cost. All corners must be cut properly. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.						L	
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail								
L						***	-		
Γ	7444								
		J]	Measur	e Sub Total:	***	· L	Sub Total:	
	Field Notes:					***************************************	****		

	Measure 2 DWF	Tank Insulation			Componen	ts			Inspected
C	comment extend p	ressure relief pipe as ne	eded		•				
					Estimated	•		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipm	DHW Tank Insulation	Each	1					
		Includes labor cost. R-10 minimum. Refer to Appendix A- Standards for Weatherization Materials and Southeast Field Guide.							
2	Labor	DHW Tank Insulation	Each	1					
C	Other Detail							·	
				Measur	e Sub Total:		,	Sub Total:	
	Field Notes:			Wran-e					

	Measure 3 Atti	c Ins. R-19			Componen	ts A-1,A	-2		Inspecte
C	attic sp access soffit ar insulatii silicone access Grade 1	es labor cost. Contractor to ace showing depth of insublements as needed and covering vent. Seal allows. Seal around chimney for fire resistant foam. Insuland weather strip with foat 1 Standards. Refer to Apples and Southeast Field Gu	ulation. But to prever holes, gawith shees stall R-30 am tape. Coendix A-S	uild insunt loose ups, and et meta fibergle Contrac	ulation dam fill insulation penetration and high te ass batt sec stor to install	around a on from er ns in attic emperatur cured to a I using Re	ttic ntering before re ttic esnet		
#	######################################				Estimated			Actual	
Ħ	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Fiberglass - R-19	SqFt	312					
2	Labor	Attic Insulation - Blown Fiberglass - R-19	SqFt	312				,,,,,	70// 1
3	Insulation	Attic Insulation - Blown Fiberglass - R-19	SqFt	312		- Sent			
4	Labor	Attic Insulation - Blown Fiberglass - R-19	SqFt	312					******
O	ther Detail								

			ı	Measure	Sub Total:		\$	ub Total:	
	Fleld Notes:		-		W				

Client ID: 80008KN0813 Alt. Client ID: KNOX

Work Order Name: WO/80008KN0813/1 Report Run On: 5/8/2010

Page 4 of 8

Measure	4 Flo	or Ins. R-19			Componen	ts F-1			Inspected
Commen	before Standa subfloc (e.g. st compre	es labor cost. Contractor's installing insulation. Contracts. Insulation is installed or above (paper side again aves for blankets). Insulations. Refer to Appendictheast Field Guide.	ractor to in I to mainta est subfloot tion to ha	nstall u ain per or) inclu ve NO	sing Resnet manent cont uding necess gaps, voids,	Grade 1 act with t sary supp or	he orts		
_				****	Estimated	<u>'</u>		Actual	
# Material /	Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulatio	n	Floor Insulation <i>-</i> Fiberglass Batts - R-19	SqFt	1144					
2 Labor		Floor Insulation - Fiberglass Batts - R-19	SqFt	1144					
Other Detail	<u> </u>								
				<u> </u>					
				Measur	e Sub Total:			Sub Total:	
Field Note	es:	, <u>uni</u>	*****	PAU					

Measure 5 Fix I	mproper Venting (Cloth	es Dryer)	Componen	ts	****	***************************************	Inspected
protrudii is 15 fee	ents installed with dampering through pipe. Must be let. No changes allowed. Frization Materials and Sou	vented to Refer to A	outsio Attachn	le of home. I nent A- Stan	√laximun	n length	ı	
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Dryer Vent w/ Metal Piping (upto 15' in length)	Each	1					
	Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.							
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:						***************************************	_	

Client ID: 80008KN0813 Alt. Client ID: KNOX Work Order Name: WO/80008KN0813/1 Report Run On: 5/8/2010

Version 8.6.0 Page 6 of 8

		Improper Venting of Bar haust Fan	throom		Componen	ts				Inspected
C	Comment Bath V Attach Guide.	ents installed to outside of ment A- Standards for We	home. Natherization	o char on Mai	nges allowed terials and So	Refer to	o :Fi	eld		, to
					Estimated				Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	-	Qty	Unit Cost	Total
1	Health and Safel	y Bath Vent w/ Piping to Outside	Each	1						
		Refer to Attachment A- Standards for Weatherization Materials and Southeast Field Guide.								
2	Labor	Labor	Each	1][
(Other Detail									
			ı	Measur	e Sub Total:]	s	ub Total:	
	Field Notes:	100	******		7740	****				

Measure 7 Fix	v Ventilation Inadequate	(Attic) 2	2	Componen	fs		******	Inspected
chang	/ents installed on High pa 50 of the area of space b es allowed. Refer to Attac als and Southeast Field G	eing ventil: hment A-	ated.1/	2 high and 1/	2 low. N	JO.	a	
NOTE	Do not install roof vents	on front pa	art of h					
# Majorial/Labara	•		-	Estimated	74.		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safet 	y Roof Vents	Each	2		***			
	Location					J L	ا ا	
² Labor	Labor	Each	2					
Other Detail							J (

] []		
L								
		ı	Measure	Sub Total:		s	ub Total:	
Field Notes:			T	7				
	701. 701. 701. 701.		-744	, , , , , , , , , , , , , , , , , , ,			***	
		Work Or	dor Gra	ad Total:		O	~	
		WOIN OIL	uer Grai	iu rotai:		Grand	Total:	